

INSTRUCTIONS

CAT. # 2CT3A-6 TACHOMETER

RPM 0-3500.
FOR USE ON 6 IMP DUCATTI IGN.


! IMPORTANT !

This tach. uses the A.C. signal from the grey lead on ducatti ign.

Calibrated for 6 IMP. per/rev.

Do not connect tach to pulse or trigger coils.

Maximum input voltage is 30 volts A.C.



Install the instrument in a 2 1/16 inch hole for in convenient operating place at least 12 inches from compass. Use U clamp to hold in place.

On the rear of the instrument there are connecting pins with corresponding numbers.

Use patch cable provided to connect the instrument to the appropriate power source.

For use on ducatti ign. Connect pin #2 to the grey lead. Connect pin #5 to engine ground.

Patch cable may be lengthened with out affecting accuracy of the unit. Using 20-22 gauge wire is recommend.

WARRANTY

WESTACH INSTRUMENTS are made with the highest quality material and workmanship. With reasonable care, instruments will give long and satisfactory service. WESTACH INSTRUMENTS are guaranteed against defective material and workmanship for 12 months from the manufacturing date. For complete details go to www.westach.com

WESTACH
©

WESTBERG MFG. INC.
www.westach.com